


## Analogue Gas Meter Protection Bracket



**Front View**




**Side View**



**Partially Assembled View**



**Top View**



**Yellow section added later**

### **TAKE NOTE**



**Ensure breather hole is not completely obscured**

Ensure that the bracket does NOT obscure the relief valve from being able to operate normally by it being located too close to the valve.

If this happens (as shown) a hole or slot may need to be cut into the metal to allow this valve to *breathe* normally.